


Note: Unused port was terminated with a WR-12 load Circular to WR-12 adapters were inserted as required



Note: Unused port was terminated with a WR-12 load Circular to WR-12 adapters were inserted as required